



Inuvialuit Land Administration

PO Box 290, Tuktoyaktuk, NT X0E 1C0
Tel: 867 977 7100 Fax: 867 977 7101

June 22, 2011

Eli Nasogaluak
Coordinator, EIRB
107 Mackenzie Road, Suite 204
P.O. Box 2120
Inuvik, NT X0E 0T0

Email: eirb@jointsec.nt.ca

RE: Inuvialuit Land Administration's Review of the Inuvik-Tuktoyaktuk Highway EIS for Conformity with the TOR

The ILA has compared the contents of the submitted Inuvik-Tuktoyaktuk Highway Environmental Impact Statement to the EIRB's Terms of Reference. During its review of the EIS, the ILA was unable to locate a table containing inspection requirements listed in section 13.2 *Compliance Monitoring* of the TOR.

Specifically the TOR states:

The developer shall prepare a table with inspection requirements. This table will be updated throughout the life of the project to reflect the current conditions of any applicable permits, licences, and approvals. The table shall include, at a minimum, information on what inspection activity will be taken and how frequently and during which period the inspection will occur.

The ILA appreciates the opportunity to provide comments on the EIS. If there are any questions or concerns, please feel free to contact me.

Emily Borsy

Emily Borsy
Chief Land Administrator (Acting)
Inuvialuit Land Administration
PO Box 290
Tuktoyaktuk, NT X0E 1C0
Phone: (867) 977-7107
Fax: (867) 977-7101
Email: eborsy@irc.inuvialuit.com